

# *Oil Field Environmental Incident Summary*

**Incident:** 20190906083053      **Notice:** 9/6/2019      08:30      **Occurred:** 9/5/2019      12:25

**Responsible Party:** EOG RESOURCES, INC.

**Well Operator:** EOG RESOURCES, INC.

**Well Name:** FERTILE 48-0905H

**Field Name:** PARSHALL

**Well File #:** 20622

**Facility ID #:**

**County:** MOUNTRAIL

**Twp Rng Sec Qtr:** 151 90 9

**Location Description:**

**Submitted By:** Danielle Dupay

**Received By:**

**Contact Info:**  
Danielle Dupay  
600 17TH ST., STE 1000N  
DENVER CO 80202

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Equipment Failure

**Release Contained:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	30	Barrels	30	Barrels		
<b>Other</b>						

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Env. Impacts:**

None

**Action Taken/Planned:**

A Hydrovac was used to remove the contaminated material and a skidsteer will remove other contaminated rock and it will be taken to disposal.

**Wastes Disposal Location:**

Stanley Secure Facility

**Other Agencies Involved:**

## Updates

---

**Date:** 9/6/2019

**Status:** Reviewed - Assigned to Other Agency

**No Further Action:**

**Author:** O'Gorman, Brian

**Notes:**

Release, due to equipment failure was contained on the facility site according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA and EPA.

**Updated Volumes and Contaminant** None at the time of this update