

Oil Field Environmental Incident Summary

Incident: 20190911105018 **Notice:** 9/11/2019 10:50 **Occurred:** 9/10/2019 08:00

Responsible Party: QEP ENERGY COMPANY
Well Operator: QEP ENERGY COMPANY
Well Name: TANK BATTERY 15-23Y (KIRKLAND 2BH,1 &15E CTB)
Field Name: GRAIL
Well File #:
Facility ID #: 226227-01
County: MCKENZIE
Twp Rng Sec Qtr: 149 95 23 SW SE
Location Description:
Submitted By: Nick Turner
Received By:
Contact Info: Daniel Nameniuk
 1050 17TH ST STE 500
 DENVER CO 80265

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:
Nearest Water Well:

Type of Incident: Pump Leak
Release Contained: Yes - Within Dike
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	30	Barrels	30	Barrels		

Brine
Other

Oth Rel. Contaminant:
Date Inspected:
Clean Up Concluded:
Written Report Recd:
Risk Evaluation:

Flash fire

Areal Extent:

Potential Env. Impacts:

Spill contained within berm. Potential environmental impacts to soil.

Action Taken/Planned:

Isolated point of release. Replace gasket.

Wastes Disposal Location:

Secure Disposal in Keene, ND

Other Agencies Involved:

Updates

Date: 9/11/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: DeVries, Taylor

Notes:

According to the incident report, the release was contained to the well pad. NDIC takes oversight.

Updated Volumes and Contaminant None at the time of this update