

Oil Field Environmental Incident Summary

Incident: 20190912075932 **Notice:** 9/12/2019 07:59 **Occurred:** 9/11/2019 07:35

Responsible Party: LANDTECH ENTERPRISES, LLC
Well Operator: LANDTECH ENTERPRISES, LLC
Well Name: WAHLSTROM 1-10
Field Name: ELK
Well File #: 9774
Facility ID #:
County: MCKENZIE
Twp Rng Sec Qtr: 151 102 10 NW NE
Location Description: 14293 35th St NW Alexander, ND 58831
Submitted By: Tara Messer
Received By:

Contact Info: Kirk Johnson
PO BOX 1560
SIDNEY MT 59270-1560

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	80	Barrels	80	Barrels		

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

none

Areal Extent:

Potential Env. Impacts:

none

Action Taken/Planned:

Called trucking companies to vac up the spill. The Landtech crew went to location immediately to repair the leak and attach new fittings. When the rain is done the crew will finish the clean up.

Wastes Disposal Location:

Landtech Elk disposal.

Other Agencies Involved:

Updates

Date: 9/12/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: DeVries, Taylor

Notes:

According to the incident report the release of 80 barrels of brine was contained to the well pad. NDIC takes oversight.

Updated Volumes and Contaminant None at the time of this update