

Oil Field Environmental Incident Summary

Incident: 20190913080851 **Notice:** 9/13/2019 08:08 **Occurred:** 9/12/2019 16:30

Responsible Party: EQUINOR ENERGY LP
Well Operator: EQUINOR ENERGY LP
Well Name: MARTIN 32-31 1-H
Field Name: ROSEBUD
Well File #: 21498
Facility ID #:
County: WILLIAMS
Twp Rng Sec Qtr: 154 102 32
Location Description:
Submitted By: Jimmy Dickson
Received By:
Contact Info: Jimmy Dickson
6300 BRIDGE POINT PKY, BLDG 2
SUITE 100
AUSTIN TX 78730

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Other

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Gallons	4	Gallons		

Brine

Other

Oth Rel. Contaminant: A valve was left open to build gas pressure in the 2 phase separator.

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

none

Areal Extent:

Area around storm water discharge.

Potential Env. Impacts:

Vegetation on outside of well site in the area around storm water drain valve discharge.

Action Taken/Planned:

Shut down well. closed valves to stop release

Wastes Disposal Location:

To be Determined. most likely 13 mile Secure

Other Agencies Involved:

Updates

Date: 9/13/2019 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: DeVries, Taylor

Notes:

According to the incident report the release was not contained to the well pad. Further follow up is needed.

Updated Volumes and Contaminant None at the time of this update

Date: 9/13/2019 **Status:** Inspection - Vegetation Check **No Further Action:**

Author: Crowdus, Kory

Notes:

On location 9/13/2019, at 9:56am. Release was off site in the SW corner of pad. Flowed down hillside and appeared to end near the fence line at the bottom. Company was on site to determine extent of release. Further follow up is required.

Updated Volumes and Contaminant None at the time of this update

Date: 11/20/2019 **Status:** Inspection - Vegetation Check **No Further Action:**

Author: Crowdus, Kory

Notes:

On location 11/20/2019, at 3:09pm. No impacts seen at this time. Follow-up to check on vegetation growth.

Updated Volumes and Contaminant None at the time of this update

Date: 6/3/2020 **Status:** Inspection - No Action Required **No Further Action:**

Author: Crowdus, Kory

Notes:

On location 6/3/2020, at 10:42am. No remaining impacts seen at this time. No further follow-up is required.

Updated Volumes and Contaminant None at the time of this update