Oil Field Environmental Incident Summary

					•	
Incident: 20190915185		e: 9/15/2019	18:57	Occurred: 9/15/201	9 09:22	
Responsible Party:	BURLINGTON RESOURCES OIL & GAS COMPANY LP					
Well Operator:	BURLINGTON RESOURCES OIL & GAS COMPANY LP					
Well Name:	AMANDA 21-14H					
Field Name:	HAYSTACK BUTTE					
Well File #:	18841					
Facility ID #:						
County:	MCKENZIE					
Twp Rng Sec Qtr:	148 98 14					
Location Description:						
Submitted By:	Kelsy Waggaman					
Received By:						
Contact Info:	Kelsy Waggam	Kelsy Waggaman				
	925 North Eldri	dge Pkwy				
	HOUSTON TX 77079					
Affected Medium:	Well/Facility Sc	Well/Facility Soil				
General Land Use:	Well/Facility Sit	Well/Facility Site				
Near. Occupied Bldg:						
Nearest Water Well:						
Type of Incident:	Fire					
Release Contained:	Yes - Within Dike					
Reported to NRC:	No	No				
Spilled	Units	Recovered	Units	Followup	Units	
Oil				0		
Brine				0		
Other				0		
				Ũ		
Oth Rel. Contaminant:	No oil spill or oi combustion.	il combustion. F	ire resulte	-	nting and	
Oth Rel. Contaminant: Date Inspected:	•	il combustion. F	ire resulte	-	nting and	
	combustion.	il combustion. F	ire resulte	-	nting and	
Date Inspected:	combustion.	il combustion. F	ire resulte	-	nting and	
Date Inspected: Clean Up Concluded:	combustion. 9/20/2019	il combustion. F	ire resulte	-	nting and	
Date Inspected: Clean Up Concluded: Written Report Recd:	combustion. 9/20/2019 2/28/2020	il combustion. F	ire resulte	-	nting and	
Date Inspected: Clean Up Concluded: Written Report Recd: Risk Evaluation:	combustion. 9/20/2019 2/28/2020	I combustion. F	ire resulte	-	nting and	
Date Inspected: Clean Up Concluded: Written Report Recd: Risk Evaluation: Risks have been mitigat	combustion. 9/20/2019 2/28/2020 ed, None.		ire resulte	-	nting and	
Date Inspected: Clean Up Concluded: Written Report Recd: Risk Evaluation: Risks have been mitigat Areal Extent:	combustion. 9/20/2019 2/28/2020 ed, None. to flare pit on loc		ire resulte	-	nting and	
Date Inspected: Clean Up Concluded: Written Report Recd: Risk Evaluation: Risks have been mitigat Areal Extent: N/A. Fire was contained	combustion. 9/20/2019 2/28/2020 ed, None. to flare pit on loc	ation.	ire resulte	-	nting and	

Operator shut in the well, blocked in the well, and used his fire extinguisher to extinguish the flame. PRV Internals will be inspected, maintenance to check all flare stack equipment integrity before restarting the well.

Wastes Disposal Location:

N/A

Other Agencies Involved:

Updates

Date: 9/16/2019	Status: Reviewed - Assigned to Other Agency	No Further Action: 🗸
Author: Crowdus, K	ory	
Notes:		
Fire on location. NDIC	C retains oversight.	

Updated Volumes and Contaminant None at the time of this update