

Oil Field Environmental Incident Summary

Incident: 20191108185440 **Notice:** 11/8/2019 18:54 **Occurred:** 11/8/2019 17:30

Responsible Party: Corcoran oilfield services
Well Operator: CONTINENTAL RESOURCES, INC.
Well Name: RAVIN 1-1H
Field Name:
Well File #: 18584
Facility ID #:
County: MCKENZIE
Twp Rng Sec Qtr: 150 97 1
Location Description: Spill onsite
Submitted By: chansy wolff
Received By:

Contact Info: chansy wolff
 34729 Co Rd 119
 sidney MT 59270

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:
Nearest Water Well:

Type of Incident: Vessel Leak
Release Contained: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	20	Barrels	20	Barrels		
Other						

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

NA

Areal Extent:

Potential Env. Impacts:

facility soil

Action Taken/Planned:

Corcoran is currently cleaning up their mess

Wastes Disposal Location:

TBD

Other Agencies Involved:

Updates

Date: 11/12/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: O'Gorman, Brian

Notes:

Release, due to a vessel leak, was contained on the facility site according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update