

Oil Field Environmental Incident Summary

Incident: 20191112102657 **Notice:** 11/12/2019 10:26 **Occurred:** 11/11/2019 20:02

Responsible Party: Diversified Environmental & Energy Services, LLC

Well Operator: SAMSON OIL AND GAS USA, INC

Well Name: Musial 1-18H

Field Name: PRONGHORN

Well File #: 16132

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 150 101 18 NW SW

Location Description:

Submitted By: Gilbert Thompson

Received By:

Contact Info: Rasheen Hughes
2860 W. Holly St
Sidney MT 59270

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Other

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	120	Barrels	117	Barrels	117	barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 11/13/2019

Written Report Recd: 6/11/2020

Risk Evaluation:

None

Areal Extent:

Potential Env. Impacts:

Contaminated top soil on the well pad

Action Taken/Planned:

Vac truck has recovered 117 barrels of the water from the dike. Contaminated dirt will be scrapped and disposed of properly.

Wastes Disposal Location:

The waste will be hauled to a third party disposal.

Other Agencies Involved:

Updates

Date: 11/12/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: O'Gorman, Brian

Notes:

According to the report, brine was released and contained on the well site. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update