

# Oil Field Environmental Incident Summary

**Incident:** 20191115092417      **Notice:** 11/15/2019    09:24      **Occurred:** 11/14/2019    09:00

**Responsible Party:** Henry Hill Oil Services  
**Well Operator:** HENRY HILL OIL SERVICES, LLC  
**Well Name:** Dvorak-Seidl 1-27-3c  
**Field Name:** LITTLE KNIFE  
**Well File #:** 8277  
**Facility ID #:**  
**County:** DUNN  
**Twp Rng Sec Qtr:** 145   97   27  
**Location Description:**  
**Submitted By:** Matt Azure  
**Received By:**  
**Contact Info:** Matt Azure  
120 26th street east suit 200  
Williston ND 58801

**Affected Medium:** Well/Facility Soil  
**General Land Use:** Well/Facility Site  
**Near. Occupied Bldg:** 1 Mile  
**Nearest Water Well:** 1 Mile  
**Type of Incident:** Equipment Failure  
**Release Contained:** Yes - Within Dike  
**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	5	Barrels	5	Barrels		
<b>Other</b>						

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

Na

**Areal Extent:**

**Potential Env. Impacts:**

NA

**Action Taken/Planned:**

line and tank drained and part replaced.

**Wastes Disposal Location:**

back into site tanks.

**Other Agencies Involved:**

Nicole NDIC

## **Updates**

---

**Date:** 11/18/2019      **Status:** Reviewed - Assigned to Other Agency

**No Further Action:** ☒

**Author:** DeVries, Taylor

**Notes:**

According to the incident report, the release was contained to the well pad. NDIC takes oversight.

**Updated Volumes and Contaminant**    None at the time of this update