

# Oil Field Environmental Incident Summary

**Incident:** 20191212135742      **Notice:** 12/12/2019 13:57      **Occurred:** 12/11/2019 16:24

**Responsible Party:** Arrow Water, LLC

**Well Operator:**

**Well Name:**

**Field Name:**

**Well File #:**

**Facility ID #:**

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 150 94 26 NW NW

**Location Description:** Pipeline right of way

**Submitted By:** Mitch Lagerstrom

**Received By:**

**Contact Info:** Mitch Lagerstrom  
10702 Highway 73  
Keene ND 58847

**Affected Medium:** Topsoil

**General Land Use:** Other - Described Above

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Pipeline Leak

**Release Contained:** Yes - On Pipeline ROW

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	553	Barrels				

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

No immediate health hazards

**Areal Extent:**

**Potential Env. Impacts:**

Impact to soil

**Action Taken/Planned:**

Hydrovac water, scoop and haul impacted soil, backfill with clean soil

**Wastes Disposal Location:**

**Other Agencies Involved:**

## **Updates**

---

**Date:** 12/12/2019    **Status:** Reviewed - Assigned to Other Agency    **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

Release on pipeline ROW. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.

**Updated Volumes and Contaminant**    None at the time of this update