

Oil Field Environmental Incident Summary

Incident: 20191219113724 **Notice:** 12/19/2019 11:37 **Occurred:** 12/18/2019 18:00

Responsible Party: BIG DISPOSAL CARTWRIGHT
Well Operator: BIG DISPOSAL CARTWRIGHT, LLC
Well Name: Cartwright SWD #1
Field Name: GLASS BLUFF
Well File #: 90285

Facility ID #:
County: MCKENZIE
Twp Rng Sec Qtr: 151 102 30 SE NE

Location Description: 1/2 Mile South of 200 on 149th NW. SWD Location with AG use surrounding.

Submitted By: Brent Lansberg

Received By:

Contact Info: Brent Lansberg
 1525 Bioscience Drive
 Worthington MN 56187

Affected Medium: Well/Facility Soil
General Land Use: Other - Described Above

Near. Occupied Bldg: 0.8 Mile

Nearest Water Well: 0.8 Mile

Type of Incident: Tank Overflow

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	200	Barrels	180	Barrels		

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

All fluid is contained within the lined containment area and little to no risk of further movement. Most bbls have already been sucked up.

Areal Extent:

Potential Env. Impacts:

None anticipated

Action Taken/Planned:

We have lowered the max allowable levels in the tank and are installing a bullhorn siren to alarm at high tank levels.

Wastes Disposal Location:

Indian Hills Disposal

Other Agencies Involved:

Updates

Date: 12/19/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: DeVries, Taylor

Notes:

According to the incident report, the release was contained within the tank berm. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update