

Oil Field Environmental Incident Summary

Incident: 20200201171239 **Notice:** 2/1/2020 17:12 **Occurred:** 2/1/2020 04:30

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: WOLD FEDERAL 42-1-1H

Field Name: SAND CREEK

Well File #: 33481

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 153 97 1 NE SE

Location Description: Latitude: 48.105262 Longitude: -103.08887

Submitted By: Allison Christensen

Received By:

Contact Info:
Allison Christensen
1700 Lincoln, Ste 4700
DENVER CO 80203

Affected Medium: Topsoil

General Land Use: Badlands Terrain

Near. Occupied Bldg: 1.5 Mile

Nearest Water Well: 0.5 Mile

Type of Incident: Equipment Failure

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels	9.5	Barrels	9.5	barrels
Brine	10	Barrels	9.5	Barrels	9.5	barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 2/10/2020

Written Report Recd: 2/28/2020

Risk Evaluation:

No immediate risks

Areal Extent:

Approximately 250' X 600' on the N/NE side of location

Potential Env. Impacts:

Minor impacts to offsite vegetation.

Action Taken/Planned:

All wells on location were shut-in and flares were isolated. One Call submitted and completed. Maintenance crews arrived on location to begin onsite and offsite remediation.

Wastes Disposal Location:

Indian Hills

Other Agencies Involved:

NDDEQ, BLM

Updates

Date: 2/3/2020 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: Stockdill, Scott

Notes:

According to the incident summary this spill impacted areas off of location. Follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 2/5/2020 **Status:** Inspection - Vegetation Check **No Further Action:**

Author: DeVries, Taylor

Notes:

Inspection date: 2/5/2020

Arrived on location at 1340. The release occurred on the little hill by the flare. There is some oil staining on the grass. There are two full roll-away bins on site with soil and grass. Further follow-up is needed in the spring and summer months to assess vegetation regrowth.

Photos were taken and can be found in the report folder.

Updated Volumes and Contaminant None at the time of this update

Date: 2/13/2020 **Status:** Correspondence - Vegetation Check **No Further Action:**

Author: Stockdill, Scott

Notes:

Email from responsible party.

"...Attached is the Follow-up Report for the Wold Federal 42-1-1H release that occurred on 2-1-2020...."

Full email in the report folder.

Updated Volumes and Contaminant None at the time of this update

Date: 4/2/2020 **Status:** Correspondence - Vegetation Check **No Further Action:**

Author: Stockdill, Scott

Notes:

Emailed company requesting more information regarding samples taken by the hired consultant.

Updated Volumes and Contaminant None at the time of this update

Date: 4/2/2020 **Status:** Correspondence - Vegetation Check **No Further Action:**

Author: Stockdill, Scott

Notes:

Email from responsible party.

"...Here are the sample results for this release...."

Full emails and samples in report folder.

Updated Volumes and Contaminant None at the time of this update

Date: 9/10/2020 **Status:** Inspection - No Action Required **No Further Action:**

Author: Stockdill, Scott

Notes:

Arrived on location 3:04 9/10/2020.

No sign of contamination or contaminants. Vegetation is doing well in area.

No follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update