Oil Field Environmental Incident Summary

Incident: 20200209145607 Notice: 2/9/2020 14:56 Occurred: 2/8/2020 10:20

Responsible Party: WHITING OIL AND GAS CORPORATION Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: LOOMER 44-33TFHU

Field Name: BANKS
Well File #: 31150

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 152 99 33 SE SE

Location Description: Latitude: 47.9359544, Longitude: -103.3497620

Submitted By: Allison Christensen

Received By:

Contact Info: Allison Christensen

1700 Lincoln, Ste 4700

DENVER CO 80203

Affected Medium: Topsoil
General Land Use: Cultivated
Near. Occupied Bldg: 1 Mile
Nearest Water Well: 1 Mile

Type of Incident: Stuffing Box Leak

Release Contained: No Reported to NRC: No

SpilledUnitsRecoveredUnitsFollowupUnits2Barrels1.5Barrels2barrels

Brine Other

Oil

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 2/17/2020 Written Report Recd: 2/28/2020

Risk Evaluation:

No immediate risk noted

Areal Extent:

Approximately 60' X 120' mist to the East of flare stacks

Potential Env. Impacts:

Minor impacts to facility soil and light mist to offsite vegetation.

Action Taken/Planned:

The wellhead was cleared of salt obstruction and rubbers replaced. Remediation of onsite facility soil is in progress.

Wastes Disposal Location:

To an approved disposal

Other Agencies Involved:

NDDEQ

Updates

Date: 2/10/2020 Status: Reviewed - Follow-up Required No Further Action: ✓

Author: Suess, Bill

Notes:

This incident was not fully contained on the well pad. Follow-up is required.

Updated Volumes and Contaminant None at the time of this update

Date: 2/18/2020 Status: Inspection - Vegetation Check No Further Action: ✓

Author: Stockdill, Scott

Notes:

Arrived on location 11:30 2/13/2020.

No sign of contamination at the time of inspection. The impacted grass has been cut and removed.

Follow-up in spring to check on vegetation.

Updated Volumes and Contaminant None at the time of this update

Date: 2/19/2020 Status: Correspondence - Vegetation Check No Further Action: ✓

Author: Stockdill, Scott

Notes:

Email from responsible party.

"...Attached is the Follow-up Report for the Loomer 44-33TFHU release that occurred on 2-8-2020...."

Full email and attachments in Report folder.

Updated Volumes and Contaminant None at the time of this update

Date: 8/12/2020 Status: Inspection - No Action Required No Further Action: ✓

Author: Stockdill, Scott

Notes:

Arrived on location 5:03 8/12/2020.

No sign of contamination or contaminants. Vegetation in area is doing well.

No follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update