

# *Oil Field Environmental Incident Summary*

**Incident:** 20200211133030      **Notice:** 2/11/2020    13:30    **Occurred:** 2/10/2020    18:00

**Responsible Party:** NexTier  
**Well Operator:** XTO ENERGY INC  
**Well Name:** ARLYS 34X-31H  
**Field Name:** SIVERSTON  
**Well File #:** 36134  
**Facility ID #:**  
**County:** MCKENZIE  
**Twp Rng Sec Qtr:** 150 97 31  
**Location Description:**  
**Submitted By:** Kaylan Dirkx  
**Received By:**  
**Contact Info:** Amy Brummage  
 2225 West Villard Street  
 Dickinson ND 58601

**Affected Medium:** Well/Facility Soil  
**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**  
**Nearest Water Well:**

**Type of Incident:** Tank Overflow  
**Release Contained:** Yes - On Constructed Well Site  
**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	44	Barrels	44	Barrels	44	barrels
<b>Other</b>	230	Barrels	230	Barrels	230	barrels

**Oth Rel. Contaminant:** Fresh Water (FW)

**Date Inspected:**  
**Clean Up Concluded:** 2/25/2020  
**Written Report Recd:** 3/3/2020

**Risk Evaluation:**  
 None

**Areal Extent:**

**Potential Env. Impacts:**

Minimal - majority of fluid was contained within impermeable containment. All released volume has been recovered.

Spill contained on pad: 252 bbls inside impermeable containment (211.53 bbls FW, 40.47 bbls PW), 22 bbls outside impermeable containment (18.47bbls FW and 3.53 bbl PW)

**Action Taken/Planned:**

Valves were closed and released fluid was recovered.

**Wastes Disposal Location:**

Re-used on-site. Any remaining cleanup notes will be captured in the NDIC Follow-up report.

**Other Agencies Involved:**

## **Updates**

---

**Date:** 2/11/2020

**Status:** Reviewed - Assigned to Other Agency

**No Further Action:**

**Author:** Suess, Bill

**Notes:**

Incident was contained on an E & P exempt facility. NDIC retains oversight.

**Updated Volumes and Contaminant** None at the time of this update