

Oil Field Environmental Incident Summary

Incident: 20200213184006 **Notice:** 2/13/2020 18:40 **Occurred:** 2/13/2020 07:30

Responsible Party: P. O. & G. Operating, LLC
Well Operator: P.O. & G. OPERATING, LLC
Well Name: GRIGGS 1-9
Field Name: WILLMEN
Well File #: 16466
Facility ID #:
County: DUNN
Twp Rng Sec Qtr: 142 97 9 NW NW
Location Description: N/A
Submitted By: Zach Dworshak
Received By:

Contact Info: Mel Smith
5847 SAN FELIPE, STE 3200
HOUSTON TX 77057

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Fire
Release Contained: Yes - On Facility Site

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine

Other

Oth Rel. Contaminant: N/A

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

N/A

Areal Extent:

N/A

Potential Env. Impacts:

N/A

Action Taken/Planned:

No spill was caused, roustabout crew will cleanup burnt tin/insulation. Treater burners are checked daily by the pumper, this incident occurred while the pumper was away and there was equipment failure.

Wastes Disposal Location:

Tin and insulation will be disposed of at landfill or the proper facility.

Other Agencies Involved:

Updates

Date: 2/14/2020 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Suess, Bill

Notes:

Incident was reported as a fire that remained on the well pad. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update