

# *Oil Field Environmental Incident Summary*

**Incident:** 20200214101823      **Notice:** 2/14/2020    10:18    **Occurred:** 2/13/2020    15:30

**Responsible Party:**    PETRO HARVESTER OPERATING COMPANY, LLC

**Well Operator:**        PETRO HARVESTER OPERATING COMPANY, LLC

**Well Name:**            E-M KALMBACH 5-9 SWD 1

**Field Name:**            WOBURN

**Well File #:**            15174

**Facility ID #:**

**County:**                BURKE

**Twp Rng Sec Qtr:**      162   90   5   SE NE

**Location Description:**

**Submitted By:**        Bill Bender

**Received By:**

**Contact Info:**        Bill Bender  
5005 LYNDON B JOHNSON FREEWAY  
SUITE 700  
DALLAS TX 75244

**Affected Medium:**    Well/Facility Soil

**General Land Use:**   Well/Facility Site

**Near. Occupied Bldg:** 5558 Feet

**Nearest Water Well:** 5558 Feet

**Type of Incident:**     Equipment Failure

**Release Contained:**   Yes - Within Dike

**Reported to NRC:**     No

	<i>Spilled</i>	<i>Units</i>	<i>Recovered</i>	<i>Units</i>	<i>Followup</i>	<i>Units</i>
<b>Oil</b>						
<b>Brine</b>	20	Barrels	20	Barrels		
<b>Other</b>						

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

No immediate health hazard or explosive atmosphere risk.

**Areal Extent:**

**Potential Env. Impacts:**

No impact to surface water or ground water.

**Action Taken/Planned:**

The free liquids were removed from inside containment with a vacuum truck. The affected nipple was replaced.

**Wastes Disposal Location:**

Recovered liquids were recycled on location.

**Other Agencies Involved:**

## **Updates**

---

**Date:** 2/14/2020      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

According to the incident report, the release was contained to the well pad. NDIC takes oversight.

**Updated Volumes and Contaminant**    None at the time of this update