

# Oil Field Environmental Incident Summary

**Incident:** 20200214172255      **Notice:** 2/14/2020    17:22    **Occurred:** 2/13/2020    19:00

**Responsible Party:** BURLINGTON RESOURCES OIL & GAS COMPANY LP

**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP

**Well Name:** BIG BEND 21-2TFH

**Field Name:** CAMEL BUTTE

**Well File #:** 26092

**Facility ID #:**

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 151 96 2

**Location Description:**

**Submitted By:** Kelsy Waggaman

**Received By:**

**Contact Info:** Kelsy Waggaman  
925 N. Eldridge Pkwy  
HOUSTON TX 77084

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Fire

**Release Contained:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0.1	Barrels			0.1	barrels

**Brine**

**Other**

**Oth Rel. Contaminant:** N/A

**Date Inspected:**

**Clean Up Concluded:** 2/16/2020

**Written Report Recd:** 2/28/2020

**Risk Evaluation:**

All immediate risks have been mitigated. Site is secured.

**Areal Extent:**

N/A

**Potential Env. Impacts:**

Oil mist on snow inside tank berm.

**Action Taken/Planned:**

Work order has been submitted for clean-up. Internal review of event will be completed.

**Wastes Disposal Location:**

TBD

**Other Agencies Involved:**

Local Fire Department

## **Updates**

---

**Date:** 2/18/2020      **Status:** Reviewed - Assigned to Other Agency

**No Further Action:**

**Author:** Suess, Bill

**Notes:**

Incident was contained on a wellpad. NDIC retains oversight.

**Updated Volumes and Contaminant**    None at the time of this update