

# *Oil Field Environmental Incident Summary*

**Incident:** 20200717135609      **Notice:** 7/17/2020    13:56    **Occurred:** 7/16/2020    11:18

**Responsible Party:** WHITING OIL AND GAS CORPORATION

**Well Operator:** WHITING OIL AND GAS CORPORATION

**Well Name:** BARTLESON 11-32H

**Field Name:** SANISH

**Well File #:** 17285

**Facility ID #:**

**County:** MOUNTRAIL

**Twp Rng Sec Qtr:** 153 92 32

**Location Description:** 30' off Bartleson 11-32H CTB pad to the Southeast. Fire Burned approx. 20' x 20' area of pasture.

**Submitted By:** Shelby Lego

**Received By:**

**Contact Info:** Shelby Lego  
1700 Lincoln, Ste 4700  
DENVER CO 80203

**Affected Medium:** Topsoil

**General Land Use:** Pasture

**Near. Occupied Bldg:** 1.2 Mile

**Nearest Water Well:** 1.2 Mile

**Type of Incident:** Fire

**Release Contained:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
--	----------------	--------------	------------------	--------------	-----------------	--------------

**Oil**

**Brine**

<b>Other</b>	0.2	Gallons	0.2	Gallons		
--------------	-----	---------	-----	---------	--	--

**Oth Rel. Contaminant:** Soot build up on H/L Steffes combo flare.

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

No immediate health hazards

**Areal Extent:**

20' x 20' pasture area burned

**Potential Env. Impacts:**

Burned pasture land. Lease Operator stamped fire out and monitored area for approx. 3 hours.

**Action Taken/Planned:**

Maintain and inspect Steffes flares for soot build up.

**Wastes Disposal Location:**

No waste at this time.

**Other Agencies Involved:**

N/A

## Updates

---

**Date:** 7/17/2020      **Status:** Reviewed - Follow-up Required

**No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

According to the incident report, there was a fire off location and a release of soot build up from the flare. Further follow-up is needed.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 7/21/2020      **Status:** Inspection - More Follow-up Required

**No Further Action:**

**Author:** Lund, Dylan

**Notes:**

Arrived on location at 1505 on 7/21/2020.

30ft SE of flare there is a 20'x20' area that is burned. Vegetation check is needed next year.

Photos were taken and can be found in incident folder.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 10/12/2020      **Status:** Inspection - No Action Required

**No Further Action:**

**Author:** Stockdill, Scott

**Notes:**

Arrived on location 4:06 10/12/2020.

No sign of contamination or contaminants at the time of inspection.

No follow-up is necessary.

**Updated Volumes and Contaminant**    None at the time of this update