Oil Field Environmental Incident Summary

Incident: 20200727121	733 Notic	e: 7/27/2020	12:17	Occurr	ed: 7/26/2020	0 01:05
Responsible Party:	Oasis Petroleum North America LLC					
Well Operator:	OASIS PETROLEUM NORTH AMERICA LLC					
Well Name:	DAWSON 5494 42-12 3B					
Field Name:	ALKALI CREEK					
Well File #:	33922					
Facility ID #:						
County:	MOUNTRAIL					
Twp Rng Sec Qtr:	154 94 12	SE SW				
Location Description:						
Submitted By:	Dustin Anderson					
Received By:						
Contact Info:	Dustin Anderson					
	1001 FANNIN STE 1500					
	HOUSTON TX 77002					
Affected Medium:	Well/Facility Soil					
General Land Use:	Well/Facility Site					
Near. Occupied Bldg:						
Nearest Water Well:						
Type of Incident:	Other					
Release Contained:	Yes - Within Dike					
Reported to NRC:	No					
Spilled	Units	Recovered	Units		Followup	Units
Oil						
Brine 100	Barrels	95	Barrels			
Other						
Oth Rel. Contaminant: Produced water						
Date Inspected:						
Clean Up Concluded:						
Written Report Recd:						
Risk Evaluation:						
low - released fluid was	contained within t	he dikes on the	e well pad			
Areal Extent:						
80 feet wide by 150 feet long						
Potential Env. Impacts	2					
Low	_					
Action Taken/Planned: Increase site surveillanc						
	-					
Wastes Disposal Location:						
D360						
R360 Other Agencies Involve	od					

Updates

 Date:
 7/27/2020
 Status:
 Reviewed - Assigned to Other Agency
 No Further Action:
 ✓

 Author:
 Lund, Dylan
 Notes:
 Notes:
 Vertical Action
 Vertical Action

According to the incident report, the release was confined to the well pad. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update