Oil Field Environmental Incident Summary

| Incident: 202007280830 | | | otice: 7/28/2020 | 08:36 | Occurred: 7/26/2020 | 0 12:00 |
|---|---------|---------------------------------------|------------------|-------|---------------------|---------|
| Responsible Party: | | HESS BAKKEN INVESTMENTS II, LLC | | | | |
| Well Operator: | | HESS BAKKEN INVESTMENTS II, LLC | | | | |
| Well Name: | | EN-DOBROVOLNY A-155-94-2413 H-4,5,6,7 | | | | |
| Field Name: | | MANITOU | | | | |
| Well File #: | | | | | | |
| Facility ID #: | | 228096-01 | | | | |
| County: | | MOUNTRAIL | | | | |
| Twp Rng Sec Qtr: | | 155 94 24 SW SE | | | | |
| Location Description: | | 48.2276,-102.7098 | | | | |
| Submitted By: | | Kathleen Kangas | | | | |
| Received By: | | | | | | |
| Contact Info: | | Mark Donnelly | | | | |
| | | 3015 16TH ST SW | | | | |
| | | MINOT ND 58701 | | | | |
| Affected Medium: | | Well/Facility Soil | | | | |
| General Land Use: | | Well/Facility Site | | | | |
| Near. Occupied Bldg: | | 2 Mile | | | | |
| Nearest Water Well: | | 2 Mile | | | | |
| Type of Incident: | | Other | | | | |
| Release Contained: | | Yes - On Constructed Well Site | | | | |
| Reported to NRC: | | No | | | | |
| | Spilled | Units | Recovered | Units | Followup | Units |
| Oil | 0.3 | Gallons | | | | |
| Brine | 10.5 | Barrels | | | | |
| Other | | | | | | |
| Oth Rel. Contaminant: | | | | | | |
| Date Inspected: | | | | | | |
| Clean Up Concluded: | | | | | | |
| Written Report Recd: | | | | | | |
| Risk Evaluation: | | | | | | |
| Produced water impacts to the well facility soil/scoria and bermed water. Small amount of oil impacts to scoria/soil. | | | | | | |

Areal Extent:

Produced water impacts on N and W of facility scoria/soil/stormwater. The gate valve was closed.

Potential Env. Impacts:

Impacts to well facility scoria and soil and also to bermed stormwater.

Action Taken/Planned:

The RO arrived onsite and immediately closed the produced water load line valve. RO also contacted EHS. Sheriff's report was also filed. Field environmental assessment was done.

Wastes Disposal Location:

An approved waste disposal facility.

Other Agencies Involved:

Local Law Enforcement

Updates

 Date:
 7/28/2020
 Status:
 Reviewed - Assigned to Other Agency
 No Further Action:

 Author:
 Crowdus, Kory

 Notes:
 Release remained on location according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update