

Oil Field Environmental Incident Summary

Incident: 20200731085335 **Notice:** 7/31/2020 08:53 **Occurred:** 7/30/2020 13:00

Responsible Party: WPX ENERGY WILLISTON, LLC

Well Operator: WPX ENERGY WILLISTON, LLC

Well Name: ELK 16-21H CTB

Field Name: VAN HOOK

Well File #:

Facility ID #: 218794-01

County: MOUNTRAIL

Twp Rng Sec Qtr: 150 92 16 NW NW

Location Description:

Submitted By: Adam Ries

Received By:

Contact Info: Adam Ries
3500 One Williams Center- MD38
TULSA OK 74172

Affected Medium: Topsoil

General Land Use: Pasture

Near. Occupied Bldg: 0.2 Mile

Nearest Water Well: 0.7 Mile

Type of Incident: Fire

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	5	Gallons	4	Gallons		

Oth Rel. Contaminant: Natural gas condensate was released from the flare.

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

Fire was put out with dry chemical extinguishers. No other immediate risks.

Areal Extent:

890 square feet on location and 325 square feet off location

Potential Env. Impacts:

Impacts to well/facility soil and pastureland. No other potential environmental impacts.

Action Taken/Planned:

Knockout tank and pump were isolated for repairs. Burnt and impacted soil will be removed.

Wastes Disposal Location:

Solid waste landfill

Other Agencies Involved:

MHA Energy/TAT Environmental/BIA

Updates

Date: 8/3/2020

Status: Reviewed - Assigned to Other Agency

No Further Action: ☒

Author: DeVries, Taylor

Notes:

According to the incident report, there was a fire off of the well pad. Location is within MHA Nation. Report forwarded to MHA environmental, BIA, and EPA.

Updated Volumes and Contaminant None at the time of this update