

Oil Field Environmental Incident Summary

Incident: 20200801215730 **Notice:** 8/1/2020 21:57 **Occurred:** 8/1/2020 12:14

Responsible Party: SCOUT ENERGY MANAGEMENT LLC

Well Operator: SCOUT ENERGY MANAGEMENT LLC

Well Name: MARCUS 1

Field Name: INDIAN HILL

Well File #: 10854

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 153 101 34 NE SW

Location Description: 48.033070 -103.655090

Submitted By: Beki Sample

Received By:

Contact Info:
 Beki Smple
 4901 LBJ FREEWAY, STE 300
 DALLAS TX 75244

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels		
Brine	2	Barrels	2	Barrels		

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

N/A

Areal Extent:

4' x 20'

Potential Env. Impacts:

N/A

Action Taken/Planned:

The well was shut in, a vac truck was dispatched and recovered the emulsion on the ground. Recovered emulsion was taken to the slop tank at the Hoehn Disposal

Wastes Disposal Location:

Hoehn Disposal slop tank and the R360 Disposal for the solids

Other Agencies Involved:

Updates

Date: 8/3/2020 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: DeVries, Taylor

Notes:

According to the incident report, the release remained on location. NDIC takes oversight.

Updated Volumes and Contaminant None at the time of this update