Oil Field Environmental Incident Summary

Responsible Party:XTO ENERGY INCWell Operator:XTO ENERGY INCWell Name:RAVIN 21X-15 CTB

Field Name: SIVERSTON

Well File #:

Facility ID #: 234074-01
County: MCKENZIE

Twp Rng Sec Qtr: 150 97 15 NE NW

Location Description:

Submitted By: Kaylan Dirkx

Received By:

Contact Info: Kaylan Dirkx

110 WEST 7TH STREET

FORT WORTH TX 76102

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Fire

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil Brine Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: Written Report Recd: Risk Evaluation:

Fire was extinguished by Watford City Fire Department. No injuries

Areal Extent:

Potential Env. Impacts:

Minimal- fire was contained on site and was extinguished.

Action Taken/Planned:

Watford City Fire Department dispatched and extinguished the fire

Wastes Disposal Location:

N/A

Other Agencies Involved:

Watford City Fire Department, CSB, McKenzie Co Emergency Response

Updates

Date: 8/4/2020 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the incident report, the fire was contained to the well pad. NDIC takes oversight.

Updated Volumes and Contaminant None at the time of this update