

Oil Field Environmental Incident Summary

Incident: 20200804144839 **Notice:** 8/4/2020 14:48 **Occurred:** 8/4/2020 01:20

Responsible Party: WHITE OWL ENERGY SERVICES (US) INC.

Well Operator: WHITE OWL ENERGY SERVICES (US) INC.

Well Name: BARSTAD SWD 1

Field Name: ALGER

Well File #: 90171

Facility ID #:

County: MOUNTRAIL

Twp Rng Sec Qtr: 156 93 25 NW NW

Location Description:

Submitted By: Elizabeth Simek

Received By:

Contact Info: Jerold Marden
P.O. BOX 1953
DICKINSON ND 58602

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

All fluid stayed inside our tank battery containment. All fluid that was released and all contaminated rocks and soil will be sucked up & disposed of.

Areal Extent:

Potential Env. Impacts:

All fluid stayed inside our tank battery containment. Tanks are being cleaned. All fluid that was released and all contaminated rocks and soil will be sucked up and disposed of.

Action Taken/Planned:

All fluid stayed inside our tank battery containment. Tanks are being cleaned. All fluid that was released and all contaminated rocks and soil will be sucked up and disposed of.

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 8/6/2020

Status: Reviewed - Assigned to Other Agency

No Further Action: ☒

Author: DeVries, Taylor

Notes:

According to the incident report, the release was contained to the well pad. NDIC takes oversight.

Updated Volumes and Contaminant None at the time of this update