

# *Oil Field Environmental Incident Summary*

**Incident:** 20200805124026      **Notice:** 8/5/2020      12:40      **Occurred:** 8/4/2020      14:10

**Responsible Party:** HESS BAKKEN INVESTMENTS II, LLC

**Well Operator:** HESS BAKKEN INVESTMENTS II, LLC

**Well Name:** HA-ROLFSRUD-152-96- 1720H-1

**Field Name:** WESTBERG

**Well File #:** 18820

**Facility ID #:**

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 152 96 17 NE NW

**Location Description:** 47.9915,-102.9967

**Submitted By:** Kathleen Kangas

**Received By:**

**Contact Info:**  
Robert April  
3015 16TH ST SW  
MINOT ND 58701

**Affected Medium:** Well/Facility Soil

**General Land Use:** Other - Described Above

**Near. Occupied Bldg:** 2.8 Mile

**Nearest Water Well:** 2.8 Mile

**Type of Incident:** Treater Popoff

**Release Contained:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	4.5	Barrels				

**Brine**

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

light mist of oil coating 4 treaters, production pipe, saltwater building, and 2 tanks on the North side of the road.

**Areal Extent:**

Light misting in area (triangle) 220FT X 220FT X 220FT towards the North.

**Potential Env. Impacts:**

Light misting of oil to equipment confirmed. Will determine if any vegetation/soil was impacted.

**Action Taken/Planned:**

RO responded to Treater PSI HH shutdown alarm. SRO was notified. The facility was shut down. Vac truck was dispatched to pull fluids from the treater. Remediation will be completed. The Oil Dump will be repaired or replaced.

**Wastes Disposal Location:**

An approved waste disposal facility.

**Other Agencies Involved:**

## Updates

---

**Date:** 8/6/2020      **Status:** Reviewed - Follow-up Required

**No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

According to the incident report, the release of crude oil was not contained to the well pad. Further follow-up is needed.

**Updated Volumes and Contaminant**   None at the time of this update

---

**Date:** 8/19/2020      **Status:** Inspection - Vegetation Check

**No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

Inspection Date: 8/19/2020

Arrived on location at 0940. The location of the release is the grassy divider between the two well pads ( 47.991983 -102.996288). This section has been mowed. There is no staining visible. Another inspection is recommended to make sure vegetation grows back.

Photos were taken and can be found in the report folder.

**Updated Volumes and Contaminant**   None at the time of this update

---

**Date:** 6/29/2021      **Status:** Inspection - Vegetation Check

**No Further Action:**

**Author:** Wax, Pete

**Notes:**

On site 8:02AM, 6/29/2021. Photographs collected. Nice clean pad. Walked exterior boundary. No evidence of previous impacts. No further action required.

**Updated Volumes and Contaminant**   None at the time of this update