

Oil Field Environmental Incident Summary

Incident: 20200806100848 **Notice:** 8/6/2020 10:08 **Occurred:** 8/5/2020 10:47

Responsible Party: XTO ENERGY INC
Well Operator: XTO ENERGY INC
Well Name: GEORGE-BANG FEDERAL 21X-19 CTB
Field Name: LOST BRIDGE
Well File #:
Facility ID #: 220521-01
County: DUNN
Twp Rng Sec Qtr: 148 96 19
Location Description: 1.80 bbls on pad and 0.2 bbls produced water 170' off pad down along lease road in rocked ditch
Submitted By: Natalie Steiner
Received By:
Contact Info: Natalie Steiner
 110 WEST 7TH STREET
 FORT WORTH TX 76102
Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site
Near. Occupied Bldg:
Nearest Water Well:
Type of Incident: Pipeline Leak
Release Contained: No
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	2	Barrels	1.8	Barrels		
Other						

Oth Rel. Contaminant: none

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

none - personal on site at time of release - location was immediately shut in

Areal Extent:

0.20 bbls of produced water ran along lease road into rocked ditch (170')

Potential Env. Impacts:

Minimal - 1.8 bbl on site, 0.2 off site

Action Taken/Planned:

Lines were shut in immediately, repairs and remediation will be made after one call is cleared. Land owner has been contacted, waiting for responds

Wastes Disposal Location:

Blue Butte

Other Agencies Involved:

NDDEQ

Updates

Date: 8/6/2020 **Status:** Reviewed - Follow-up Required

No Further Action:

Author: DeVries, Taylor

Notes:

According to the incident report, the release was not contained to the well pad. Further follow-up is needed.

Updated Volumes and Contaminant None at the time of this update

Date: 8/18/2020 **Status:** Inspection - No Action Required

No Further Action:

Author: DeVries, Taylor

Notes:

Inspection Date: 8/18/2020

Arrived on location at 1300. According to the incident report, the release ran down the berm and into the rip rap ditch way. The grass is growing on both sides of the hill and in the ditch area. The hill right off of the road and going down into the ditch looks to have been seeded. That is growing very nicely. No further follow-up is needed at this time.

Photos were taken and can be found in the report folder.

Updated Volumes and Contaminant None at the time of this update

Date: 9/3/2020 **Status:** Correspondence - No Action Required

No Further Action:

Author: DeVries, Taylor

Notes:

Taylor DeVries sent a No Further Action letter dated September 3, 2020.

Updated Volumes and Contaminant None at the time of this update