

Oil Field Environmental Incident Summary

Incident: 20201222104004 **Notice:** 12/22/2020 10:40 **Occurred:** 12/22/2020 07:00

Responsible Party: PETRO-HUNT, L.L.C.
Well Operator: PETRO-HUNT, L.L.C.
Well Name: USA 153-95-22C-15-2H
Field Name: CHARLSON
Well File #: 22334
Facility ID #:

County: MCKENZIE
Twp Rng Sec Qtr: 153 95 22

Location Description:
Submitted By: Derek Enderud
Received By:
Contact Info: Derek Enderud
 PO BOX 935
 BISMARCK ND 58502

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:
Nearest Water Well:

Type of Incident: Tank Overflow
Release Contained: Yes - Within Dike
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	136	Barrels	136	Barrels		
Other						

Oth Rel. Contaminant:
Date Inspected:
Clean Up Concluded:
Written Report Recd:
Risk Evaluation:

None

Areal Extent:

Potential Env. Impacts:
 None, all within lined dike.

Action Taken/Planned:

Fluid was removed this morning. Tank will be washed down on a calm day to prevent overspray.

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 12/22/2020 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: DeVries, Taylor

Notes:

According to the incident report, the release was contained to the well pad. NDIC takes oversight.

Updated Volumes and Contaminant None at the time of this update