

Oil Field Environmental Incident Summary

Incident: 20201228081049 **Notice:** 12/28/2020 08:10 **Occurred:** 12/27/2020 14:30

Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Name: GLADSTONE 1-2-3-25 TRIPLE

Field Name: N/A

Well File #:

Facility ID #: 23355301

County: MCKENZIE

Twp Rng Sec Qtr: 153 97 26

Location Description:

Submitted By: Robyn Espinoza

Received By:

Contact Info: Robyn Espinoza
925 N. Eldridge Pkwy
HOUSTON TX 77084

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Fire

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

None

Areal Extent:

Potential Env. Impacts:

None

Action Taken/Planned:

Review line purging standards to keep lines clear of condensate. remove any stained or charred scoria

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 12/28/2020 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Stockdill, Scott

Notes:

According to the incident summary, this incident involved a fire on location. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update