

General Environmental Incident Summary

Incident: 10532 **Notice:** 7/17/2020 1300 **Occurred:** 7/17/2020 0810

DEM Incident No:

No Further Action: ☐

Responsible Party: Teraflex

County: McKenzie

Twp Rng Sec Qtr: 150 99 23

Lat Long + Method: 47.79758 -103.30650 Interpolation from map

Location Description: This is a temporary exit from 85 b just west of 14th st on the south side of the road. accident was right on the edge of the road

Submitted By Info: Chuck Gohl
1015 58st West
williston ND

Received By Info:

Contact Info: Chuck Gohl
1015 58st West
Williston ND 58801

Affected Medium: 03 - soil

Near. Occupied Bldg: 2000 Feet

Type of Incident: Vehicle Accident

Release Contained: Yes

Reported to NRC: No

Contaminant: Diesel

Volume of Release: 30 gallons

Duration of Release: 3 hours

Agriculture Related: No

EPA Extremely Hazardous Substance: Unknown

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

One truck pulled out in front of other truck

Risk Evaluation:

None

Potential Env. Impacts:

None material was cleaned up immediately.

Action Taken/Planned:

Vacuum trailer was already on site and vacuumed up majority of the liquid, remaining gravel that was impacted was scrapped up and placed in side dump.

Wastes Disposal Location:

Material will be tested as an industrial waste then disposed of at Secure Energy 13 mile landfill.

Other Agencies Involved:

Local Law Enforcement, Local Emergency Manager

Updates

Date: 7/17/2020 **Status:** Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

According to the incident report, there was a release of 30 gallons of diesel. Further follow-up is needed.

Updated Volume: None at the time of this update

Date: 8/20/2020 **Status:** Inspection - No Action Required

Author: DeVries, Taylor

Notes:

Inspection Date: 8/20/2020

Arrived at provided GPS coordinates. Report states that the release occurred right along the entrance. Did not observe any staining at time of inspection. The grass looks healthy and undisturbed as well. No further follow-up is needed.

Photos were taken and can be found in the report folder.

Updated Volume: None at the time of this update

Date: 9/15/2020 **Status:** Inspection - No Action Required

Author: Kaiser, Don

Notes:

Visited site on 09-09-2020 at 1:00. Visited with company representative on site to verify location. Company representative informed me that vacuum trailer was on site for cleanup of liquid and that rest of impacted gravel was removed. No appearance of staining on gravel or road. Photos are in incident report folder.

Updated Volume: None at the time of this update