

General Environmental Incident Summary

Incident: 10534

Notice: 7/17/2020

Occurred: 7/17/2020 10:5

DEM Incident No:

No Further Action:

Responsible Party: ZMIX

County: Williams

Twp Rng Sec Qtr: 157 96 17

Lat Long + Method: 48.43022 -103.11370 Interpolation from map

Location Description: 70th street and between 112th and 113th street

Submitted By Info: rey Cortez
1309 11th st west apt 104
williston ND 58801

Received By Info:

Contact Info: Rey Cortez
1309 11th st west apt 104
williston ND 58801

Affected Medium: 04 - water and soil

Near. Occupied Bldg: 5 Miles

Type of Incident: Vehicle Accident

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: motor oil

Volume of Release:

Duration of Release: 30 minutes

Agriculture Related: No

EPA Extremely Hazardous Substance: No

Number of Fatalities:

Number of Injuries:

Cause of Incident:

the driver was driving to close to the shoulder when it collapse causing the truck to go to the opposite side in a wetland.

Risk Evaluation:

affected water ans soil

Potential Env. Impacts:

the wetland .

Action Taken/Planned:

res environmental team show up to place absorbents pad , absorbents sock as well

Wastes Disposal Location:

the

Other Agencies Involved:

NDDDES, Local Emergency Manager

Updates

Date: 7/17/2020 **Status:** Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

According to the incident report, the release was not contained and got into a wetland area. Further follow-up is needed.

Updated Volume: None at the time of this update

Date: 7/20/2020 **Status:** Inspection - More Follow-up Required

Author: Lund, Dylan

Notes:

Arrived on location at 1345 on 7/20/2020.

The south side ditch of 70th St NW at GPS location is disturbed from the accident with a visible sheen in the surrounding water. There is also a strong scent of oil. Met and talked with RP environmental personnel. Exchanged business cards for future communication regarding this spill and sample results. Follow-up required.

Photos were taken and can be found in incident folder.

Updated Volume: None at the time of this update

Date: 9/4/2020 **Status:** Correspondence - More Follow-up Required

Author: Lund, Dylan

Notes:

Emailed RP requesting updates on the clean up process. RP personnel sent documentation showing clean up efforts taken and a disposal receipt. Follow-up required to ensure impacted area has been fully cleaned. Samples may be necessary. Email and documentation is in report folder.

Updated Volume: None at the time of this update

Date: 8/18/2021 **Status:** Inspection - Vegetation Check

Author: Lund, Dylan

Notes:

Arrived on location at 4:00pm on 8-18-2021.

Water in south ditch where accident happened was dried up. Cattails and other vegetation in the area from the previous inspection are still growing healthily. There is no remaining contamination or environmental concern. No follow-up required.

Photos were taken and can be found in the incident folder.

Updated Volume: None at the time of this update