## General Environmental Incident Summary

 Incident:
 10549

 Notice:
 8/10/2020
 0800
 Occurred:
 8/8/2020
 1500

DEM Incident No: No Further Action: ✓

**Responsible Party:** Straight Line Directional LLC

County: Dunn

Twp Rng Sec Qtr: 146 96 18

Lat Long + Method: 47.47210 -102.97010 Interpolation from map

Location Description: Go north on a 113th ave it winds around the west side of the mountain.

Travel roughly 9 miles ROW will be on east side. Release happened north

of ROW up the hill 300' feet

Submitted By Info: Ryan Olsen

2865 Finley St.

Lincoln ND 58504

Received By Info:

**Contact Info:** 

8090 6 th Ave. SE

Linton ND 58552

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Inadvertent Release

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Bentonite Mud

Volume of Release: 420 gallons

**Duration of Release:** 1 hours **Agriculture Related:** No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities: Number of Injuries: Cause of Incident:

**Unstable Ground Conditions** 

Risk Evaluation:

No immediate risk

Potential Env. Impacts:

No environmental impacts

Action Taken/Planned:

Release was contained with silt fence and straw waddles. Cleaned release up by washing it down with fresh water and use a vac truck.

Wastes Disposal Location:

Other Agencies Involved:

## **Updates**

Date: 8/10/2020 Status: Reviewed - No Action Required

Author: Suess, Bill

Notes:

This incident appears to be the same as Incident #10551 and will be tracked under that incident.

**Updated Volume:** None at the time of this update