

General Environmental Incident Summary

Incident: 10636

Notice: 12/25/2020

Occurred: 12/25/2020 0145

DEM Incident No:

No Further Action:

Responsible Party: FAS LLC

County: McKenzie

Twp Rng Sec Qtr: 153 94 16

Lat Long + Method: 48.07700 -102.77550 Calculated

Location Description: Cal Frac Continental Angus Federal 7-9H
NOTE: Unable to determine the Township, Range, and Section. Choose an option so we could report the spill to the state in a timely manner.

Submitted By Info: Megan Zettlemoyer

24501 Ecorse Road

Taylor MI 48180

Received By Info:

Contact Info:

24501 Ecorse Road

Taylor MI

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Spill

Release Contained: Yes

Reported to NRC: No

Contaminant: Diesel

Volume of Release: 50 gallons

Duration of Release:

Agriculture Related: No

EPA Extremely Hazardous Substance: No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

To be determined.

Risk Evaluation:

None

Potential Env. Impacts:

Soil

Action Taken/Planned:

Vacuum truck extracted the free standing diesel from the ground. Fuel is contained. There is engineered containment under the pad.

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 12/25/2020 **Status:** Reviewed - Follow-up Required

Author: Lund, Dylan

Notes:

According to the incident report, diesel fuel was released and potentially impacted soils. Follow-up required to make sure release was contained onsite.

Based on the lat/long, the correct TRS is 15309416. It has been updated in the database.

Updated Volume: None at the time of this update

Date: 1/6/2021 **Status:** Correspondence - More Follow-up Required

Author: Suess, Bill

Notes:

Contacted the RP and received an assessment report on 1/4/2021. A copy of the Assessment Report is in the incident folder. An onsite inspection is needed to verify remediation.

Updated Volume: None at the time of this update

Date: 11/3/2021 **Status:** Correspondence - More Follow-up Required

Author: Suess, Bill

Notes:

This incident has been re-assigned to K. Crowdus.

Updated Volume: None at the time of this update

Date: 3/23/2022 **Status:** Inspection - No Action Required

Author: Wax, Pete

Notes:

On site 2:30. Clear, calm, 50 degrees. Pad is clean and well cared for, no sign of incident can be found. Image collected. No risk to water. Off site 2:50. No further action required.

Updated Volume: None at the time of this update