

General Environmental Incident Summary

Incident: 5292

Notice: 12/20/2016

Occurred: 12/15/2016

DEM Incident No:

No Further Action:

Responsible Party: CHS Transportation

County: McHenry

Twp Rng Sec Qtr: 154 80 17

Lat Long + Method: 48.15693 -100.99390 Interpolation from map

Location Description: 5126 19th Ave N Velva ND approx. location on map

Submitted By Info: Eric Pearson
Cenex Harvest States
4115 27th Ave N
Grand Forks ND 58203

Received By Info:

Contact Info:
4115 27th Ave n
Grand Forks ND 58203

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Tank Overflow

Release Contained: Yes

Reported to NRC: No

Contaminant: Dyed diesel

Volume of Release: 10 gallons

Duration of Release:

Agriculture Related: No

EPA Extremely Hazardous Substance: Unknown

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Farmer said the material would fit in tank. Did not fit. Driver shut down as soon as it started to overflow.

Risk Evaluation:

None

Potential Env. Impacts:

None

Action Taken/Planned:

All material was cleaned up dug up from site and is being disposed of at the Sawyer landfill approx. 2 ton of material.

Wastes Disposal Location:

sawyer landfill

Other Agencies Involved:

Updates

Date: 12/20/2016 **Status:** No Further Action Requested

Author: Schiermeister, Robin

Notes:

Release has been cleaned up and contamination disposed of. No further follow-up is necessary at this time.

Updated Volume: None at the time of this update

Date: 2/17/2017 **Status:** Inspection

Author: Striebel, Ivana

Notes:

On-site at 11:20 am on 2/17/2017, partly cloudy, 37 deg F, calm. Wasn't able to find anyone on the farm, found newly excavated area around tanks, saw no evidence of spill, smelled nothing. No photos taken. Recommend closing this incident.

Updated Volume: None at the time of this update