

General Environmental Incident Summary

Incident: 5337 **Notice:** 3/9/2017 1245 **Occurred:** 3/8/2017 1500

DEM Incident No:

No Further Action:

Responsible Party: Plains Marketing

County: McKenzie

Twp Rng Sec Qtr: 152 95 6 SW

Lat Long + Method: 48.01099 -102.87970 Navigation quality GPS

Location Description: Three miles north of Hwy 2 on Hwy 1806 on west side.

Submitted By Info:
Daniel Holli
Plains Marketing
PO Box 708
Belfield ND 58622

Received By Info:

Contact Info:
Daniel Holli
P.O. Box 708
Belfield ND 58622

Affected Medium: 03 - soil

Near. Occupied Bldg: 0.5 Miles

Type of Incident: Above ground valve seep

Release Contained: Yes

Reported to NRC: No

Contaminant: Crude Oil

Volume of Release: 15 gallons

Duration of Release: 8 hours

Agriculture Related: No

**EPA Extremely
Hazardous Substance:** No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

A valve seep filled and overflowed a truck unloading Getty box at the Charlson Truck Station

Risk Evaluation:

None

Potential Env. Impacts:

soil

Action Taken/Planned:

Free oil was absorbed. Contaminated soil will be excavated for disposal.

Wastes Disposal Location:

Prairies Disposal

Other Agencies Involved:

Updates

Date: 3/9/2017 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

According to the report, 15 gallons of crude oil was released onto the soil surface at the Charlson Truck Station. More follow-up needed.

Updated Volume: None at the time of this update

Date: 3/20/2017 **Status:** Inspection

Author: Schiermeister, Robin

Notes:

Arrived on site on 3-14-2017 at 17:30 CT. It was cold but sunny. Release happened at the Plains Marketing Getty box. The Getty box is still being worked on. A pile of contaminated rocks is waiting to be characterized and disposed of. The rocks are sitting on a folded up tarp. No contamination was seen outside of the perimeter. No further follow-up is needed at this time.

Updated Volume: None at the time of this update