



## **Updates**

---

**Date:** 5/23/2017      **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

**Notes:**

According to the report, .5 gallons of lean amine was released onto the surface of the ONEOK Bennie Peer plant. Further follow-up needed.

**Updated Volume:** None at the time of this update

---

**Date:** 6/19/2017      **Status:** Correspondence

**Author:** Striebel, Ivana

**Notes:**

6/19/2017-Site will be inspected during quarterly inspections.

**Updated Volume:** None at the time of this update

---

**Date:** 8/27/2019      **Status:** Inspection

**Author:** Suess, Bill

**Notes:**

Visited the site on 8/20/2019. No signs of staining or impacts were observed. Impacted materials have been removed and new rock placed at the site. No further action is warranted. No photos were taken.

**Updated Volume:** None at the time of this update

---

**Date:** 8/28/2019      **Status:** Correspondence

**Author:** Striebel, Ivana

**Notes:**

7/18/2018 - Received email from RP and it has been added to folder. No further action needed at this time.

**Updated Volume:** None at the time of this update