# General Environmental Incident Summary

**Incident:** 5511 **Notice:** 9/12/2017 1630 **Occurred:** 9/12/2017 1630

DEM Incident No: No Further Action: ✓

Responsible Party: CHS Inc. Ag Partners LLC

County: Golden Valley
Twp Rng Sec Qtr: 138 105 30

Lat Long + Method: 46.73677 -103.98040 Interpolation from map Location Description: Gravel road going north of CHS Fertilizer plant building

Submitted By Info: Jerry Eide

Cenex Harvest States - Environmental Manager

763 Willoughby Ln

Stevensville MT 59870

Received By Info:

Contact Info: Jerry Eide

307 Lovell Street

Golva ND

Affected Medium: 03 - soil
Near. Occupied Bldg: 250 Feet

**Type of Incident:** 5 gal container fell off truck

Release Contained: Yes
Reported to NRC: No

Contaminant: Ag chemical - Dicamba

Volume of Release: 5 gallons

Duration of Release: 5 minutes

Agriculture Related: Yes

**EPA Extremely** 

Hazardous Substance:NoNumber of Fatalities:0Number of Injuries:0

Cause of Incident:

5 gallon container fell off tender truck and ruptured on the gravel road

Risk Evaluation:

None

#### Potential Env. Impacts:

Should be none as excavated material has been dug up and stored in covered location on concrete until disposal is determined

### Action Taken/Planned:

Loader was used to dig up impacted soils that were brought inside CHS Fertilizer plant, on concrete and covered. Material will probably be incorporated into fertilizer and spread at an agronomic rate if property can be located. Material is housed in a safe location for time being

## Wastes Disposal Location:

We will either field apply at agronomic rate with fertilizer or if suitable field cannot be located, it will probably go to Sawyer landfill.

### Other Agencies Involved:

# **Updates**

Date: 9/12/2017 Status: Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

According to the incident report, 5 gallons of Dicamba, a broad-spectrum herbicide, was spilled on a

gravel road. Further follow-up is needed.

Updated Volume: None at the time of this update

**Date:** 9/18/2017 **Status:** Awaiting Documentation

Author: DeVries, Taylor

Notes:

Spoke with CHS employee. He was going to send pictures and a brief report on the remediation of

this release. Awaiting those documents.

Updated Volume: None at the time of this update

Date: 9/20/2017 Status: Inspection

Author: DeVries, Taylor

Notes:

Arrived on location at 1050. No visible contamination. Received summary of clean up for CHS. Photos and cleanup summary can be found in the report folder. No further action needed at this time.

Updated Volume: None at the time of this update