

# General Environmental Incident Summary

**Incident:** 5519                      **Notice:** 9/20/2017    1515    **Occurred:** 9/20/2017    1000

**DEM Incident No:**

**No Further Action:**

**Responsible Party:** Basic Energy Services

**County:** Williams

**Twp Rng Sec Qtr:** 155 103 21

**Lat Long + Method:** 48.22817    -103.94410    Interpolation from map

**Location Description:** Stateline Plant  
15071 56th Street NW  
Williston, ND 588011

**Submitted By Info:** Levi Weltikol  
ONEOK  
896 25th St SE  
Sidney MT 59270

**Received By Info:**

**Contact Info:**  
  
922 5th St E  
Williston ND 58801

**Affected Medium:** 03 - soil

**Near. Occupied Bldg:**

**Type of Incident:** pump on truck over pressured

**Release Contained:** Yes

**Reported to NRC:** Unknown

**Contaminant:** used oil

**Volume of Release:** 1 gallons

**Duration of Release:**

**Agriculture Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Number of Fatalities:**

**Number of Injuries:**

**Cause of Incident:**

Back pressure caused pump on truck to over pressure and spray a small amount of used oil.

**Risk Evaluation:**

No immediate risk

**Potential Env. Impacts:**

Due to the small nature of the spill and that it was isolated to the immediate surface soil on an active gas plant no environmental impacts are anticipated.

**Action Taken/Planned:**

Soaker pads from spill kit were deployed. impacted soil was removed and binned for future disposal.

**Wastes Disposal Location:**

Certified landfill

**Other Agencies Involved:**

## **Updates**

---

**Date:** 9/21/2017      **Status:** Reviewed - Follow-up Required

**Author:** Martin, Russell

**Notes:**

Release is within a Oneok facility. Follow-up during the quarterly inspection schedule.

**Updated Volume:** None at the time of this update

---

**Date:** 9/10/2019      **Status:** Correspondence

**Author:** Sues, Bill

**Notes:**

The site needs to be re-inspected for verification of remediation.

**Updated Volume:** None at the time of this update

---

**Date:** 12/22/2020      **Status:** Correspondence - More Follow-up Required

**Author:** Lund, Dylan

**Notes:**

RP has been contacted requesting documentation of proof of cleanup and remediation.

**Updated Volume:** None at the time of this update

---

**Date:** 7/27/2021      **Status:** Inspection - No Action Required

**Author:** Lund, Dylan

**Notes:**

Arrived on location at 9:30am on 7/27/2021.

Location where spill occurred is isolated on an active gas plant facility. There is no chance release impacted any water or vegetation. No environmental impacts are present. Only the gravel within plant boundaries was impacted and has been cleaned up. No follow-up required.

Photos were taken and can be found in the incident folder.

**Updated Volume:** None at the time of this update