

# General Environmental Incident Summary

**Incident:** 5520      **Notice:** 9/21/2017      1120      **Occurred:** 9/21/2017      1044

**DEM Incident No:**

**No Further Action:** ☒

**Responsible Party:** Oneok Rockies Midstream

**County:** McKenzie

**Twp Rng Sec Qtr:** 151 98 35

**Lat Long + Method:** 47.84953 -103.17910 Interpolation from map

**Location Description:** Graden Creek Plant  
3007 121st Avenue NW  
Watford City, ND 58854

**Submitted By Info:** Levi Weltikol  
ONEOK  
896 25th St SE  
Sidney MT 59270

**Received By Info:**

**Contact Info:** Levi Weltikol  
896 25th St SE  
Sidney MT 59270

**Affected Medium:** 03 - soil

**Near. Occupied Bldg:**

**Type of Incident:** Tank Overflow

**Release Contained:** Yes

**Reported to NRC:** Unknown

**Contaminant:** Therminol 55

**Volume of Release:** 15 gallons

**Duration of Release:**

**Agriculture Related:** No

**EPA Extremely  
Hazardous Substance:** Unknown

**Number of Fatalities:**

**Number of Injuries:**

**Cause of Incident:**

In the process of pulling oil from the system. A drum overflowed.

**Risk Evaluation:**

No immediate risk

**Potential Env. Impacts:**

Spill was small and isolated to the immediate surface soil. no environmental impacts are anticipated.

**Action Taken/Planned:**

Soaker pads have been placed until the impacted soil will be removed and taken to a certified landfill.

**Wastes Disposal Location:**

certified landfill

**Other Agencies Involved:**

## **Updates**

---

**Date:** 9/21/2017      **Status:** Reviewed - Follow-up Required

**Author:** Martin, Russell

**Notes:**

Release is within a Oneok facility. Follow-up is necessary.

**Updated Volume:** None at the time of this update

---

**Date:** 9/22/2017      **Status:** Correspondence

**Author:** Striebel, Ivana

**Notes:**

Follow-up during quarterly inspections.

**Updated Volume:** None at the time of this update

---

**Date:** 8/27/2019      **Status:** Inspection

**Author:** Suess, Bill

**Notes:**

Visited the site on 8/20/2019. No signs of staining or impacts were observed. Impacted materials have been removed and new rock placed at the site. No further action is warranted. No photos were taken.

**Updated Volume:** None at the time of this update

---

**Date:** 8/28/2019      **Status:** Correspondence

**Author:** Striebel, Ivana

**Notes:**

7/18/2018 - Received email from RP which is in the folder. No further action needed at this time.

**Updated Volume:** None at the time of this update