## **General Environmental Incident Summary**

Incident: 5564	Notice: 1	0/25/2017	<b>Occurred:</b> 10/19/2017 0918	
DEM Incident No:			No Further Action: 🗸	
Responsible Party:	Gary Ferguson			
County:	Walsh			
Twp Rng Sec Qtr:	155 53 22			
Lat Long + Method:	48.23832 -97.	43690 Inte	erpolation from map	
Location Description:	From the city of Fo miles East on 57th		. 1 mile North on County Road 6, 1.5	
Submitted By Info:	Brent Nelson			
	638 Cooper Ave			
	Suite 2			
	Grafton ND 5823	7		
Received By Info:				
Contact Info:				
	PO Box 86			
	Forest River ND 5	58233		
Affected Medium:	02 - water			
Near. Occupied Bldg:	400 Feet			
Type of Incident:	Vehicle Accident			
Release Contained:	No			
Reported to NRC:	Unknown			
Contaminant:	Field Corn			
Volume of Release:				
Duration of Release:				
Agriculture Related:	No			
EPA Extremely				
Hazardous Substance:	Unknown			
Number of Fatalities:				
Number of Injuries:				
Cause of Incident:				
Bridge collasped while semi with load or corn was crossing it.				
Risk Evaluation:				
None				
Potential Env. Impacts:				
None				
Action Taken/Planned:		_		
Corn that could be recov	arad was removed	Some remains	in channel and had reports of seeing corn	

Corn that could be recovered was removed. Some remains in channel and had reports of seeing corn in the river downstream through the city of Minto.

Wastes Disposal Location:

Other Agencies Involved:

## **Updates**

Date: 10/26/2017 Status: Reviewed - Follow-up Required

Author: DeVries, Taylor

## Notes:

According to the incident report, there was a release of field corn that got into a creek. Further followup is needed.

Updated Volume: None at the time of this update

Date: 10/26/2017 Status: Correspondence

Author: Crowdus, Kory

## Notes:

Received photos from Emergency Manager. It was reported to me that no oil or fluids from truck were released. No further follow-up required.

Updated Volume: None at the time of this update