

General Environmental Incident Summary

Incident: 5598

Notice: 1/2/2018

1601

Occurred: 1/2/2018 1100

DEM Incident No:

No Further Action:

Responsible Party: Plains Marketing

County: Dunn

Twp Rng Sec Qtr: 145 95 4

Lat Long + Method: 47.40885 -102.79430 Navigation quality GPS

Location Description: 41 Hwy 22 North Killdeer, ND

Submitted By Info: Daniel Holli
Plains Marketing
PO Box 708
Belfield ND 58622

Received By Info:

Contact Info: Daniel Holli
P.O. Box 708
Belfield, ND ND 58622

Affected Medium: 03 - soil

Near. Occupied Bldg: 0.25 Miles

Type of Incident: Pump seal leak

Release Contained: Yes

Reported to NRC: No

Contaminant: Crude Oil

Volume of Release: 0.5 barrels

Duration of Release: 8 hours

Agriculture Related: No

**EPA Extremely
Hazardous Substance:** No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Pump seal leak into earthen secondary containment berm.

Risk Evaluation:

none

Potential Env. Impacts:

soil

Action Taken/Planned:

Excavate soil onto plastic pending disposal

Wastes Disposal Location:

Chimney Butte landfill

Other Agencies Involved:

Updates

Date: 1/3/2018 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

Release, due to a pump seal leak, impacted site soils with crude oil. Further follow-up needed.

Updated Volume: None at the time of this update

Date: 1/8/2018 **Status:** Inspection

Author: Nieraeth, Shawna

Notes:

1/3/2018 - Approximately 19 F, wind less than 5 mph, cloudy. Site covered with snow. Unable to see affected area. Return in spring after snow melt. No photos taken.

Updated Volume: None at the time of this update

Date: 5/17/2018 **Status:** Inspection

Author: Suess, Bill

Notes:

Visited the site on 5/16/2018. No visual signs of impacts within the containment area. No further action is warranted. No photos taken.

Updated Volume: None at the time of this update