

General Environmental Incident Summary

Incident: 5603 **Notice:** 1/8/2018 1540 **Occurred:** 1/8/2018 1400

DEM Incident No:

No Further Action: ☒

Responsible Party: Magellan

County: Cass

Twp Rng Sec Qtr: 139 49 4

Lat Long + Method: 46.87806 -96.87917 Address matching

Location Description: Magellan Fargo Terminal, 902 Main Avenue East, West Fargo, ND 58708

Submitted By Info: Trena Hallback
Magellan - Environmental Specialist
One Williams Center
OTC-8
Tulsa OK 74172

Received By Info:

Contact Info: Mark Haugen
902 Main Ave E
West Fargo ND 58708

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Valve leak

Release Contained: No

Reported to NRC: Unknown

Contaminant: gasoline

Volume of Release: 5 gallons

Duration of Release:

Agriculture Related: No

**EPA Extremely
Hazardous Substance:** Unknown

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

relief valve was not completely closed, resulting in small amount of gasoline coming out of the quick connect valve.

Risk Evaluation:

none

Potential Env. Impacts:

impacted snow

Action Taken/Planned:

sorbents used to capture liquids. Impacted snow containerized for disposal.

Wastes Disposal Location:

permitted landfill or reclaimed at recycling facility

Other Agencies Involved:

Updates

Date: 1/9/2018 ***Status:*** Reviewed - No Action Required

Author: O'Gorman, Brian

Notes:

This incident has an additional/similar entry which can be referred to as #5603. No further follow-up needed on this incident.

Updated Volume: None at the time of this update