

# General Environmental Incident Summary

**Incident:** 5605 **Notice:** 1/8/2018 1510 **Occurred:** 1/8/2018 1400

**DEM Incident No:** **No Further Action:**

**Responsible Party:** Magellan Pipeline Co.

**County:** Cass

**Twp Rng Sec Qtr:** 139 49 4

**Lat Long + Method:** 46.87718 -96.88211 Interpolation from map

**Location Description:** 902 Main Ave East, West Fargo, ND 58078

**Submitted By Info:** Brian Sieben  
Magellan Pipeline Company  
13424 W 98th St  
Lenexa KS 66215-1362

**Received By Info:**

**Contact Info:** Brian Sieben  
902 Main Ave East  
West Fargo ND

**Affected Medium:** 09 - other

**Near. Occupied Bldg:**

**Type of Incident:** 1/4" Pressure Relief Valve on 6" receive line to tank 677

**Release Contained:** Yes

**Reported to NRC:** No

**Contaminant:** gasoline

**Volume of Release:**

**Duration of Release:**

**Agriculture Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Number of Fatalities:**

**Number of Injuries:**

**Cause of Incident:**

Failure of a 1/4" pressure release valve on the 6" receive line to tank 677. It appears the ball on the quick connect test connection on the valve was compromised causing gasoline to mist from the valve.

**Risk Evaluation:**

No risk concerns associated with this release event.

**Potential Env. Impacts:**

None.

**Action Taken/Planned:**

The valve was isolated, removed, and replaced with a new pressure relief valve. Gasoline impacted snow was collected and placed in a 55-gallon drum for proper handling (discharge snow/product to sump or manage as waste). The ground is frozen and no impacts to the ground surface/subsurface were observed.

**Wastes Disposal Location:**

**Other Agencies Involved:**

NDDDES, Local Emergency Manager

## **Updates**

---

**Date:** 1/9/2018      **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

**Notes:**

According to the report, 5 gallons of gas was released and contained. Further follow-up needed.

**Updated Volume:** None at the time of this update

---

**Date:** 1/9/2018      **Status:** Correspondence

**Author:** O'Gorman, Brian

**Notes:**

Received a phone call from the company contact who explained to me that the release was within a secondary containment and that the ground was frozen so they scraped up the impacted snow and placed it in a 55 gallon drum for proper disposal. Contact will forward photos of the cleanup to the Department. Further follow-up needed.

**Updated Volume:** None at the time of this update

---

**Date:** 5/7/2019      **Status:** Inspection

**Author:** Crowdus, Kory

**Notes:**

On location 5/7/2019, at 11:12am. Walked site with Magellan personnel. No remaining impacts seen at this time. No further follow-up is required.

**Updated Volume:** None at the time of this update