

General Environmental Incident Summary

Incident: 5640

Notice: 2/22/2018 1618

Occurred: 2/22/2018 1015

DEM Incident No:

No Further Action:

Responsible Party: Plains Marketing

County: Williams

Twp Rng Sec Qtr: 155 95 12 NE NW

Lat Long + Method: 48.26894 -102.83900 Navigation quality GPS

Location Description: 10 miles south of Tioga, ND

Submitted By Info: Daniel Holli
PO Box 708
Belfield ND 58622

Received By Info:

Contact Info: Daniel Holli
P.O. Box 708
Belfield ND 58622

Affected Medium: 03 - soil

Near. Occupied Bldg: 1 Miles

Type of Incident: Tank Overflow

Release Contained: Yes

Reported to NRC: No

Contaminant: Crude oil

Volume of Release: 4 barrels

Duration of Release: 5 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance: No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Contract driver overfilled his truck while loading at the Haustveidt oil well lease

Risk Evaluation:

none

Potential Env. Impacts:

Soil

Action Taken/Planned:

Excavated contaminated soil into containment pending disposal

Wastes Disposal Location:

Prairie Disposal

Other Agencies Involved:

Updates

Date: 2/22/2018 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Notes:

Release at a non-exempt facility. Follow-up is required.

Updated Volume: None at the time of this update

Date: 4/13/2018 **Status:** Inspection

Author: Schiermeister, Robin

Notes:

Arrived on site at 14:32 on 4-9-2018. It was fair with temperatures in the 30's and cloudy. Walked to GPS point provided on the report and saw no signs of contamination. Called responsible party contact who said the release remained on the well pad by the getty box. Walked to getty box on the pad and saw no signs of contamination; however, workers were on site due to maintenance of the getty box and of the tank batteries. The contact said the soil was scraped up on the day of the release. Saw dirt stockpiled on site. No further follow-up is needed.

Updated Volume: None at the time of this update