General Environmental Incident Summary

Incident: 5641 *Notice:* 2/24/2018 2152 *Occurred:* 2/24/2018 1130

DEM Incident No: No Further Action: ✓

Responsible Party: Plains Marketing

County: McKenzie
Twp Rng Sec Qtr: 151 96 17

Lat Long + Method: 47.89937 -103.00480 Navigation quality GPS

Location Description: 5 miles southwest of Keene, ND

Submitted By Info: Daniel Holli

PO Box 708

Belfield ND 58622

Received By Info:

Contact Info: Daniel Holli

P.O. Box 708

Belfield ND 58622

Affected Medium: 03 - soil Near. Occupied Bldg: 1 Miles

Type of Incident: Tank Overflow

Release Contained:YesReported to NRC:UnknownContaminant:Crude Oil

Volume of Release: 0.5 barrels

Duration of Release: 5 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance: No Number of Fatalities: 0 Number of Injuries: 0

Cause of Incident:

Valve left open and overfilled Getty box

Risk Evaluation:

None

Potential Env. Impacts:

Soil

Action Taken/Planned:

Scraped up contaminated soil into containment pending analysis

Wastes Disposal Location:

Prairie disposal

Other Agencies Involved:

Updates

Date: 2/24/2018 Status: Reviewed - Follow-up Required

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill impacted areas not associated with exploration and

production. Follow-up is necessary.

Updated Volume: None at the time of this update

Date: 3/1/2018 Status: Inspection

Author: Crowdus, Kory

Notes:

On location 3/1/2018, at 12:25pm. Company man on site showed me release location. No signs of

release remains at this time. No further follow-up required.

Updated Volume: None at the time of this update