

# General Environmental Incident Summary

**Incident:** 5651

**Notice:** 3/8/2018

**Occurred:** 3/7/2018

**DEM Incident No:**

**No Further Action:**

**Responsible Party:** BNSF Railway

**County:** Ward

**Twp Rng Sec Qtr:** 155 82 24

**Lat Long + Method:** 48.23861 -101.16000 Interpolation from map

**Location Description:** BNSF Railway  
6400 4th Ave NE  
Minot, ND

**Submitted By Info:** Matt Richardson  
Contractor  
604 7th Street North  
Wilton ND

**Received By Info:**

**Contact Info:** Edward Pettit  
6400 4th Ave NE  
Minot ND

**Affected Medium:** 03 - soil

**Near. Occupied Bldg:** 150 Feet

**Type of Incident:** Hydraulic Line Break on Payloader

**Release Contained:** Yes

**Reported to NRC:** Unknown

**Contaminant:** Hydraulic Oil

**Volume of Release:** 8 gallons

**Duration of Release:** 1 minutes

**Agriculture Related:** No

**EPA Extremely**

**Hazardous Substance:** Unknown

**Number of Fatalities:** 0

**Number of Injuries:** 0

**Cause of Incident:**

Hydraulic line break on a Pay loader. Originally reported as a 50 gallon spill. Actual amount spilled was 8 gallons.

**Risk Evaluation:**

No immediate risk to human health.

**Potential Env. Impacts:**

No environmental impacts are expected. Impacted soil and snow was excavated and containerized for disposal.

**Action Taken/Planned:**

Impacted soil was excavated.

**Wastes Disposal Location:**

**Other Agencies Involved:**

## **Updates**

---

**Date:** 3/8/2018      **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Notes:**

According to the incident summary, this spill impacted the surrounding area. Follow-up is necessary to ensure proper cleanup.

**Updated Volume:** None at the time of this update

---

**Date:** 9/25/2018      **Status:** Awaiting Documentation

**Author:** Martin, Russell

**Notes:**

Due to limited impact indicated in report from the event and proximity to active rail lines, awaiting update from BNSF consultant before further Department review.

**Updated Volume:** None at the time of this update

---

**Date:** 9/12/2019      **Status:** Correspondence

**Author:** Suess, Bill

**Notes:**

The RP has been contacted and asked to provide a status update on this site. The DEQ is waiting on the response.

**Updated Volume:** None at the time of this update

---

**Date:** 10/2/2019      **Status:** Correspondence - No Action Required

**Author:** Martin, Russell

**Notes:**

Received cleanup report from contractor on 9/27/2019. No further follow-up required.

**Updated Volume:** None at the time of this update

---

**Date:** 12/2/2019      **Status:** Correspondence - No Action Required

**Author:** Martin, Russell

**Notes:**

Russell Martin sent a No Further Action letter dated November 29, 2019.

**Updated Volume:** None at the time of this update