# *General Environmental Incident Summary*

| | | | | |
|---|---|---|---|---|
| ***Incident:*** 5658 | | ***Notice:*** 3/15/2018 | | ***Occurred:*** 3/14/2018 |
| ***DEM Incident No:*** | | | | ***No Further Action:*** ☑ |

***Responsible Party:*** Hwy 5 Oilfield Services, LLC

***County:*** Burke

***Twp Rng Sec Qtr:*** 163   90   32

***Lat Long + Method:*** 48.89520   -102.38890   Interpolation from map

***Location Description:*** Flaxton Water Depot

***Submitted By Info:*** Samantha Slack

89483 US Hwy 281

Spencer  NE  68777

***Received By Info:***

***Contact Info:*** Christopher Goga

206 2nd St.

P.O. Box 308

Crosby  ND  58730

***Affected Medium:*** 03 - soil

***Near. Occupied Bldg:***

***Type of Incident:*** Tank Leak

***Release Contained:*** Yes

***Reported to NRC:*** Unknown

***Contaminant:*** Production water and fresh water

***Volume of Release:*** 5  gallons

***Duration of Release:***

***Agriculture Related:*** No

***EPA Extremely Hazardous Substance:*** Unknown

***Number of Fatalities:***

***Number of Injuries:***

***Cause of Incident:***

Driver error.

***Risk Evaluation:***

None.

***Potential Env. Impacts:***

None, contaminated soil was removed.

***Action Taken/Planned:***

Soil excavated.

***Wastes Disposal Location:***

***Other Agencies Involved:***

## Updates

---

**Date:** 3/16/2018        **Status:** Reviewed - Follow-up Required

**Author:** Schiermeister, Robin

**Notes:**

Release, due to a tank leak, occurred on a non E&P facility. An inspection will be needed to determine if proper clean up was conducted.

**Updated Volume:**   None at the time of this update

---

**Date:** 3/20/2018        **Status:** Inspection

**Author:** DeVries, Taylor

**Notes:**

Inspection Date: 3/20/2018

Arrived at location at 0945. There was no evidence of salt water present on the gravel by the pump house, nor the grassed area surrounding it.  The ground was still frozen and no standing liquids were visible. There was water in the storm drain.  Further follow-up in summer months to assess vegetation health.

**Updated Volume:**   None at the time of this update

---

**Date:** 9/18/2018        **Status:** No Further Action Requested

**Author:** Kannenberg, Derek

**Notes:**

There is some small washout near the drain outlet, but there does not appear to be any impacted vegetation in the area. Recommend closure.

**Updated Volume:**   None at the time of this update