General Environmental Incident Summary

Incident: 5707	Notice: 5/3/2018	0700	Occurred: 5/3/2018 0605
DEM Incident No:	Nouce. 3/3/2010	0700	No Further Action:
Responsible Party:	Darwin Moser		
County:	Stutsman		
Twp Rng Sec Qtr:	139 64 2		
Lat Long + Method:	46.88793 -98.71831	Interpolat	ion from map
Location Description:	Gas Station release from p	•	
Submitted By Info:	Anonymous Anonymous	F	
	Unknown		
	Jamestown ND		
Received By Info:	Scott Stockdill		
	Water Quality		
Contact Info:			
	Unknown		
	Medina ND		
Affected Medium:	03 - soil		
Near. Occupied Bldg:	700 Feet		
Type of Incident:	Pump Leak		
Release Contained:	No		
Reported to NRC:	Unknown		
Contaminant:	Diesel Fuel		
Volume of Release:	10 gallons		
Duration of Release:	15 minutes		
Agriculture Related:	No		
EPA Extremely			
Hazardous Substance:			
Number of Fatalities:	0		
Number of Injuries: Cause of Incident:	0		
Driver Left pump unatten	uded		
Risk Evaluation:	lueu		
Minimal the spill was released onto an impermeable surface			
Potential Env. Impacts:			
The spill could migrate to the area storm sewers however the			
Action Taken/Planned:			
Fire Department placed sand and owners of station placed floor dry to contain the release.			
Wastes Disposal Location:			
Unknown			
Other Agencies Involve	ed:		
Local Fire Department			

Updates

Date: 5/3/2018 Status: Reviewed - No Action Required

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill remained on an impermeable surface and didn't reach any storm sewers. Site is currently being cleaned up.

No follow-up is necessary.

Updated Volume: None at the time of this update