

General Environmental Incident Summary

Incident: 5712 **Notice:** 5/4/2018 1700 **Occurred:** 5/4/2018 1430

DEM Incident No:

No Further Action: ☒

Responsible Party: Cross Petroleum

County: Williams

Twp Rng Sec Qtr: 154 101 19

Lat Long + Method: 48.14160 -103.72210 Interpolation from map

Location Description: CalFrac Well Services

Submitted By Info: Alan Heltemes
5028 Bennett Industrial Drive
Williston ND 58801

Received By Info:

Contact Info: Ben Reynolds
223 9th Ave NE
Sidney MT 59270

Affected Medium: 03 - soil

Near. Occupied Bldg: 0.25 Miles

Type of Incident: Tank Leak

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Used Antifreeze

Volume of Release: 200 gallons

Duration of Release: 20 minutes

Agriculture Related: No

EPA Extremely Hazardous Substance: Unknown

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

3rd Party Vendor was transferring used antifreeze into a 330-gallon tote for disposal with the drain valve on the tote partially open

Risk Evaluation:

None

Potential Env. Impacts:

None

Action Taken/Planned:

CalFrac employees deployed spill containment booms and absorbent towels to contain all free liquids. A 3rd party Hydrovac company was called to complete the cleanup and perform the disposal of the contaminated soil.

Wastes Disposal Location:

Undetermined at this time

Other Agencies Involved:

Updates

Date: 5/4/2018 ***Status:*** Reviewed - Follow-up Required

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill impacted the surrounding area. Follow-up is necessary.

Updated Volume: None at the time of this update

Date: 5/15/2018 ***Status:*** Inspection

Author: Martin, Russell

Notes:

5/8/2018 at 15:20, on location. Met with report submitter and inspected site. No visible impact remains and, according to submitter, wastes were sent to IHD. No further follow-up required at this time.

Updated Volume: None at the time of this update