

# General Environmental Incident Summary

**Incident:** 5722

**Notice:** 5/18/2018 0940

**Occurred:** 5/17/2018 1600

**DEM Incident No:**

**No Further Action:**

**Responsible Party:** WBI Energy Transmission, Inc.

**County:** Burke

**Twp Rng Sec Qtr:** 162 91 7

**Lat Long + Method:** 48.87329 -102.54580 Navigation quality GPS

**Location Description:** Southern main entrance to Oneok Rockies Midstream, LLC facility near Lignite, ND. Directions: From Lignite, ND, head west on 2nd Ave. E towards Main Street. Turn right at the 1st cross street onto Main Street. Turn right onto 101st St. NW. Turn right onto 84th Ave. NW.

**Submitted By Info:** Kate Joyce  
WBI Energy Environmental Affairs Dept.  
2010 Montana Ave.  
Glendive MT 59330

**Received By Info:**

**Contact Info:** Mollie Hunt  
2010 Montana Ave.  
Glendive MT 59330

**Affected Medium:** 03 - soil

**Near. Occupied Bldg:** 674 Feet

**Type of Incident:** Tank Leak

**Release Contained:** Yes

**Reported to NRC:** No

**Contaminant:** Oil

**Volume of Release:** 1 gallons

**Duration of Release:** 1 minutes

**Agriculture Related:** No

**EPA Extremely Hazardous Substance:** No

**Number of Fatalities:** 0

**Number of Injuries:** 0

**Cause of Incident:**

WBI Energy was performing a blowdown of their transmission natural gas pipeline near the Oneok facility so that the line could be worked on safely. The gas/liquids from the blowdown were captured into a rented frac tank. During the blowdown, some of the accumulated liquids blew out of a hatch on the frac tank and misted onto the adjacent gravel road. The spill occurred in a matter of seconds and it is estimated that less than a gallon of oil misted onto the road - there were no puddles of oil.

**Risk Evaluation:**

None

**Potential Env. Impacts:**

None

**Action Taken/Planned:**

WBI Energy utilized their equipment (backhoe) to scrape up the contaminated soil and gravel. This was bagged and loaded onto a work truck for transport back to the WBI Energy center of pipeline operations in Glendive, MT. The soil will be analyzed prior to disposal.

**Wastes Disposal Location:**

Bagged oil-stained soil and gravel will be transported to the Glendive, MT landfill for disposal.

***Other Agencies Involved:***

***Updates***

---

***Date:*** 5/18/2018      ***Status:*** Reviewed - Follow-up Required

***Author:*** O'Gorman, Brian

***Notes:***

According to the report, 1 gallon of oil was released during a tank leak. Further follow-up needed.

***Updated Volume:*** None at the time of this update

---

***Date:*** 6/12/2018      ***Status:*** Inspection

***Author:*** DeVries, Taylor

***Notes:***

Inspection Date: 6/12/2018

Arrived on location at 1035. I observed no oil staining off of location. There were no observed dead plants or oil smell. Photos taken and added to incident folder.

No further follow-up is needed at this time.

***Updated Volume:*** None at the time of this update