

General Environmental Incident Summary

Incident: 5781 **Notice:** 7/10/2018 1438 **Occurred:** 7/10/2018 1000

DEM Incident No: **No Further Action:**

Responsible Party: Baranko Brothers Environmental

County: McKenzie

Twp Rng Sec Qtr: 151 96 20

Lat Long + Method: 47.88221 -102.99350 Interpolation from map

Location Description: Plugged and abandoned Oil well site (J.W. Westergaard 1) 2 miles S, 2 Mi W, 1 Mi S, .5 Mi East of Keene, ND

Submitted By Info: Doug Hanson
PO Box 0820
Dickinson ND 58601

Received By Info:

Contact Info: Doug Hanson
PO Box 0820
Dickinson ND 58601

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Hydraulic line release

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Hydraulic oil

Volume of Release: 0.5 gallons

Duration of Release: 2 minutes

Agriculture Related: No

EPA Extremely Hazardous Substance: Unknown

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Pin hole in hydraulic line

Risk Evaluation:

None

Potential Env. Impacts:

None

Action Taken/Planned:

Absorbant napkins and a small pan used for recovery.

Wastes Disposal Location:

Napkins will be taken to our shop and will be taken to an approved waste disposal facility.

Other Agencies Involved:

Updates

Date: 7/10/2018 **Status:** Reviewed - Follow-up Required

Author: Martin, Russell

Notes:

Release, due to hydraulic line pinhole, in an old remediation site for a plugged & abandoned well, according to the report. Follow-up is necessary.

Updated Volume: None at the time of this update

Date: 7/24/2018 **Status:** Inspection

Author: Washek, Sandi

Notes:

Arrived onsite at 10:21 AM. Weather was sunny, with wind out of the NW at 5 miles/hr. Temperature of 70 degrees F.

The area where the spill occurred was undergoing major dirt work at the time of the inspection. Area has been cleaned up and impacted soil removed. No additional follow-up needed.

Updated Volume: 0.5 gallons