

General Environmental Incident Summary

Incident: 5847

Notice: 9/12/2018 1542

Occurred: 9/12/2018 1420

DEM Incident No:

No Further Action:

Responsible Party: Magellan pipeline

County: Cass

Twp Rng Sec Qtr: 139 49 4

Lat Long + Method: 46.87806 -96.87917 Navigation quality GPS

Location Description: Magellan Fargo Terminal , 902 Main Ave E, West Fargo, ND 58708

Submitted By Info:
Trena Hallback
Magellan pipeline
One Williams Center
OTC 8
Tulsa OK 74172

Received By Info:

Contact Info:
Mark Haugen
902 Main Ave Easr
Fargo ND 58708

Affected Medium: 09 - other

Near. Occupied Bldg:

Type of Incident: Discharge hose rupture

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Biodiesel

Volume of Release: 20 gallons

Duration of Release: 5 minutes

Agriculture Related: No

EPA Extremely Hazardous Substance: Unknown

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Tank truck was offloading and the discharge hose ruptured.

Risk Evaluation:

Nonr

Potential Env. Impacts:

None, released into concrete containment

Action Taken/Planned:

Vac truck sucking up liquids, sorbets used to clean up residue.

Wastes Disposal Location:

Heritage Environmental Services

Other Agencies Involved:

Updates

Date: 9/14/2018 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

Release was at a fuel loading facility. More follow-up needed.

Updated Volume: None at the time of this update

Date: 5/7/2019 **Status:** Inspection

Author: Crowdus, Kory

Notes:

On location 5/7/2019, at 11:04am. Walked site with Magellan personnel. No remaining impacts seen at this time. No further follow-up is required.

Updated Volume: None at the time of this update